


OHIO PPE REQUIREMENTS FOR TRANSPORTERS / DRIVERS



Ohio – Canton, 2050 Central Ave. SE Canton, Ohio 44707
EPA ID # OHD 980 568 992



SPU Unloading Area (Unloading, Observing only) PPE Requirements

- Eye Protection
- Long Sleeve Shirt and Pants
- Steel-Toed Safety Shoes
- Hard Hat and Work Gloves
- High Visibility Vest or Clothing

SPU Solids Unit (to cross threshold into SPU from Unloading Pad) PPE Requirements

- Eye Protection
- Long Sleeve Shirt and Pants
- Steel-Toed Safety Shoes
- Hard Hat and Work Gloves
- Chemical Resistant Coveralls/Tyvek
- High Visibility Vest or Clothing
- Air Purifying Respirator

Dock Unloading PPE Requirements

- Eye Protection
- Long Sleeve Shirt and Pants
- Steel-Toed Safety Shoes
- Hard Hat and Work Gloves
- High Visibility Vest or Clothing

Tanker Unloading (Under Canopy) PPE Requirements

- Eye Protection
- Long Sleeve Shirt and Pants
- Steel-Toed Safety Shoes
- Hard Hat and Work Gloves
- Chemical Resistant Coveralls/Tyvek
- High Visibility Vest or Clothing

Scale / Sample Platform PPE Requirements

- Eye Protection
- Long Sleeve Shirt and Pants
- Steel-Toed Safety Shoes
- Hard Hat and Work Gloves
- High Visibility Vest or Clothing

Shaded Areas PPE Requirements

- Eye Protection
- Long Sleeve Shirt and Pants
- Steel-Toed Safety Shoes
- High Visibility Vest or Clothing

In an emergency, immediately seek instructions from an USECology employee. See map for evacuation rally points (RP)

ADDITIONAL USECOLOGY OHIO SITE TRANSPORTER / DRIVER RULES

- Drivers should tune to **CB Channel 10**, or call **330 617 4341** by phone to contact **USecology Receiving**
- Speed limit on site is 5 mph
- All drivers must wear appropriate PPE as specified on reverse
- All drivers must bring and be trained to use the appropriate personal protective equipment (PPE)
- Full and half faced respirator cartridge requirements are Unisorb or multi-containment and P100 (HEPA)
- Hard hats must be worn properly
- Drivers are prohibited from working on elevated surfaces while at the USecology Ohio facility (this includes tankers, box trucks, platforms, or any surface 6 feet above ground or higher)
- Drivers are prohibited from crossing the Tanker Unloading area into the Liquids Processing Unit.
- Wastes shipped to the facility must be placed into closed DOT approved containers; containers must prevent leaks and spills
- Drivers shall not enter any confined spaces while on-site at USecology Ohio *unless* previously authorized by US ecology Ohio Operations
- Drivers shall immediately report to USecology Management any incident, accident, or spill
- Drivers shall conduct their business on site in a safe and orderly manner

By initialing below, I certify that I have read, that I understand, and that I will follow the USecology Ohio Site Transporter / Driver Rules (listed above) as well as the Transporter / Driver PPE Requirements (on reverse):

Date: ____ / ____ / ____

Manifest / BOL Number(s): _____

Transporter: _____

Driver Initials: _____